Maryland Historical Trust

Maryland Inventory of Historic Properties number:

The bridge referenced herein was inventoried by the Maryll Historic Bridge Inventory, and SHA provided the Trust wit The Trust accepted the Historic Bridge Inventory on April determination of eligibility.	h eligibility determinations in February 2001.
MARYLAND HISTOR	UCAL TRUST
Eligibility RecommendedX	Eligibility Not Recommended
Criteria:ABCD Considerations:	_ABCDEFGNone
Comments:	
Reviewer, OPS:_Anne E. Bruder	Date:3 April 2001
Reviewer, NR Program: Peter E. Kurtze	Date:3 April 2001

MARYLAND INVENTORY OF HISTORIC BRIDGES HISTORIC BRIDGE INVENTORY MARYLAND STATE HIGHWAY ADMINISTRATION/MARYLAND HISTORICAL TRUST

MHT No. <u>BA-2857</u>

SHA Bridge No. 3012 Bridge	e name MD 7 over Little	e Gunpowder Falls (L	ittle Gunpowder Bridge)
LOCATION: Street/Road name and numl	per [facility carried] <u>N</u>	MD 7 (Philadelphia R	doad)
City/town Bradshaw		Vicinity	X
County Baltimore	······		·
This bridge projects over: I	Road Railway	Water	X Land
Ownership: State X	County	Municipal	Other
		ional Register-detern	nined-eligible district
Name of district		The Walter Constitution of the Constitution of	
BRIDGE TYPE: Timber Bridge: Beam Bridge: Stone Arch Bridge: Metal Truss Bridge	_ _	Trestle Ti	mber-And-Concrete
Movable Bridge: Swing: Vertical Lift Metal Girder Rolled Girder	Retractile	Pontoo Concrete Encased	
Plate Girder Metal Suspension		oncrete Encased	
Metal Arch			
Metal Cantilever	_		
Concrete X : Concrete Arch X Other Type Nam	Concrete Slab	Concrete Beam	_ Rigid Frame

DESCRIPTION: Setting: Urban	Small town	Rural	X
Describe Setting:			
Bridge 3012 carries MD 7 (Phi MD 7 runs northeast to southw portion of the bridge southwest State Park.	vest and Little Gunpowder Fall	s flows north	west to southeast. The
Describe Superstructure and S	Substructure:		
Bridge 3012 is a 2-span, 2-lane, (104 feet) long and has a clear out-to-out width is 8.2 meters (13.7 meters (45 feet), which supposes of four concrete abute concrete wingwalls. The bridge	roadway width of 7.3 meters (2 (27 feet). The superstructure copport a cast-in-place concrete conents and a solid shaft concre	4 feet); there onsists of two leck and parate pier. In a	e are no sidewalks. The o arches, each spanning apets. The substructure
According to the 1997 inspection report, this structure was in satisfactory condition. The deck, roadway surface and roadway approaches are in good condition, with a recent overlay of asphalt. The arch has longitudinal cracks on the edges and undersides. The edges have spalls, scaling and cracks with efflorescence, while the underside has patches and random cracks with moisture. The arch spandrel surface has light to dark stains and light erosion. The walls have patching with horizontal and map cracks with efflorescence. The pier wall has been patched with gunite but is heavily spalled and cracked on all sides. The wingwalls have also been patched and have cracks with efflorescence and edge scaling along the joints. The wingwalls are covered with vegetation.			
Discuss Major Alterations:			
According to the 1997 bridge in The parapets were replaced at		no major alt	terations to Bridge 3012.
HISTORY:			
WHEN was the bridge built: _ This date is: Actual Source of date: PlaqueX Other (specify): _State Highwa	X Estimate Design plans Coun	ty bridge file	es/inspection form Files
WHY was the bridge built?			
The bridge was constructed in increased load capacity.	response to the need for more	efficient tran	sportation network and
WHO was the designer?			

State Roads Commission

WHO was the builder?

State Roads Commission

WHY was the bridge altered?

To replace deteriorated parapets.

Was this bridge built as part of an organized bridge-building campaign?

There is no evidence that the bridge was built as part of an organized bridge building campaign.

SURVEYOR/HISTORIAN ANALYSIS:

This bridge may have N	ational Register signific	cance for its	association	with:
A - Events	B- Person			
C- Engineering/a	architectural character	\mathbf{X}		

The bridge is eligible for the National Register of Historic Places under Criterion C, as a significant example of concrete arch construction. The structure has a high degree of integrity and retains such character-defining elements of the type as spandrel walls, arch barrel and rings, concrete abutments, pier, and wingwalls.

Was the bridge constructed in response to significant events in Maryland or local history?

The advent of modern concrete technology fostered a renaissance of arch bridge construction in the United States. Reinforced concrete allowed the arch bridge to be constructed with much more ease than ever before and maintained the load-bearing capabilities of the form. As the structural advantages of reinforced concrete became apparent, the heavy, filled barrel of the arch was lightened into ribs. Spandrel walls were opened, to give a lighter appearance and to decrease dead load. This enabled the concrete arch to become flatter and multi-centered, with longer spans possible. Designers were no longer limited to the semicircular or segmental arch form of the stone arch bridge. The versatility of reinforced concrete permitted development of a variety of economical bridges for use on roads crossing small streams and rivers.

Maryland's roads and bridge improvement programs mirrored economic cycles. The first road improvement of the State Roads Commission was a 7 year program, starting with the Commission's establishment in 1908 and ending in 1915. Due to World War I, the period from 1916-1920 was one of relative inactivity; only roads of first priority were built. Truck traffic resulting from war related factories and military installations generated new, heavy traffic unanticipated by the builders of the early road system. From 1920-1929, numerous highway improvements occurred in response to the increase in Maryland motor vehicles from 103,000 in 1920 to 320,000 in 1929, with emphasis on the secondary system of feeder roads which moved traffic from the primary roads built before World War I. After World War I, Maryland's bridge system also was appraised as too narrow and structurally inadequate for the increasing traffic, with plans for an expanded bridge program to be handled by the Bridge Division, set up in 1920. In 1920 under Chapter 508 of the Acts of 1920 the State issued a bond of \$3,000,000.00 for road construction; the primary purpose of these monies was to meet the state obligations involving the construction of rural post roads. The secondary purpose of these monies was to fund (with an equal sum from the counties) the building of lateral roads.

BA-2857

The number of hard surfaced roads on the state system grew from 2000 in 1920 to 3200 in 1930. By 1930, Maryland's primary system had been inadequate to the huge freight trucks and volume of passenger cars in use, with major improvements occurring in the late 1930's.

As the nation's automotive traffic increased in the early twentieth century, local road networks were consolidated, and state highway departments were formed to supervise the construction and improvement of state roads. With a diverse topographical domain encompassing numerous small and large crossings, Maryland engineers quickly recognized the need for expedient design and construction through the standardization of bridge designs.

The concept and practice of standardization was one of the most important developments in engineering of the twentieth century. In Maryland, as in the rest of the nation, the standardized concrete types became the predominant bridge types built. In the period 1911 to 1920 (the decade in which standardized plans were introduced), beams and slabs constituted 65 percent and arches 35 percent of the extant 29 bridges built in Maryland during this period. In the following decade, 1921-1930, the beam (now the T-beam) and slab increased to 73 percent and the arch had declined to 27 percent of the 129 extant bridges; in the next decade (1931-1940), the beam and slab achieved 82 percent and arches had further declined, constituting only 18 percent of the total of extant bridges built on state-owned roads between 1931 and 1946.

Although beam and slab bridges became the utilitarian choice, it appears that the arch was selected when aesthetic as well as other site conditions were considered. The architectural treatment of extant arch bridges supports this assessment. Many of these bridges were multiple span structures with open spandrels or masonry facing. Another decorative feature of the concrete arch bridge was an open, balustrade-style parapet. Despite the popularity of ornamental arches and the increase in use of beam and slab bridges, examples of simpler, single and multiple span closed concrete arch bridges with solid parapets continued to be constructed throughout the early twentieth century.

The route of the Philadelphia Road (State Route 7) was traveled as early as 1733, when <u>Poor Richard's Almanac</u> noted the general course of the present highway. Under pressure from the federal Bureau of Public Roads in the early 1930s, the State Roads Commission planned the construction the Pulaski Highway from Baltimore to Havre de Grace in lieu of widening the old Philadelphia Road.

When the bridge was built and/or given a major alteration, did it have a significant impact on the growth and development of the area?

There is no evidence that the construction of this bridge had a significant impact on the growth and development of this area.

Is the bridge located in an area which may be eligible for historic designation and would the bridge add to or detract from the historic/visual character of the potential district?

Unknown

Is the bridge a significant example of its type?

The bridge is a good example of the State Roads Commission standard 1920s bridge plan.

BA-2857

Does the bridge retain integrity of important elements described in Context Addendum?

The bridge retains the character-defining elements of its type, as defined by the Statewide Historic Bridge Context, including spandrel walls, arch barrel and rings, concrete pier, abutments, and wingwalls, however some deterioration is evident. The parapets have been replaced, but do not significantly impact the integrity of the bridge.


Is the bridge a significant example of the work of a manufacturer, designer, and/or engineer?

This bridge is a significant example of the work of the State Roads Commission in the 1920s.

Should the bridge be given further study before an evaluation of its significance is made?

No further study of this bridge is required to evaluate its significance.

BIBLIOGRAPHY:
County inspection/bridge files SHA inspection/bridge files X Other (list):
Johnson, Arthur Newhall 1899 The Present Condition of Maryland Highways. In Report on the Highways of Maryland Maryland Geological Survey, The Johns Hopkins University Press, Baltimore.
P.A.C. Spero & Company and Louis Berger & Associates 1995 Historic Highway Bridges in Maryland: 1631-1960: Historic Context Report. Maryland State Highway Administration, Maryland State Department of Transportation, Baltimore Maryland.
State Roads Commission 1958 A History of Road Building in Maryland. Published by author, Baltimore.
Tyrrell, H. Grattan 1909 Concrete Bridges and Culverts for Both Railroads and Highways. The Myron C. Clark Publishing Company, Chicago and New York.
SURVEYOR:
Date bridge recorded December 1997
Name of surveyor Wallace, Montgomery & Associates / P.A.C. Spero & Company
Organization/Address P.A.C. Spero & Co., 40 W. Chesapeake Avenue, Baltimore, MD 21204
Phone number (410) 296-1635 FAX number (410) 296-1670






Inventory # <u>2A-2857</u>

County/State BALTII	MORE COUNTY/MD DAVE DIEHL
Date 195	
Location of Negative	SHA
Description WEST	APPROACH WOILING
EAST	•

Number 26 of 36



Inventory	#	BA-2857
-----------	---	---------

County/State	BALTIN	DAVE DIEH	MIL	FALLS
Location of 1	Negative _	SHA		
Description	SOUTH	ELEVATION	WOK	ING

Number Nof 36



Inventory # BA-2857

Name 3012-1	407	OVER	UME	GUNA	WOER	FALLS
County/State	BALT	IMUR	E cou	MTY	MO	
Name of Phot	ograph	ner	DAVE	DIE	HL	
Date 19	5					

Location of Negative SHA

Description NORTH ELEVATION LOOKING SOUTH WEST

Number 30625

Inventory # BA-2857
Name 3012-MOT WER LITTLE GUNDAUDER FALLS
County/State BALTIMORE COUNTY/MO
Name of Photographer DAVE DIEHL
Date 1 95
Location of Negative SHA

Description PLAQUE ON SOUTH PARAPET

Number Hof 36



Inventory	#	BA-2857

Name 3012-M	07 OVER	UTTLE (GUN PUNCER FALL
County/State	BALTIMORE	Coun	MIMO
Name of Photo	ographer DA	RAE	12
Date 195	>		

Location of Negative SHA

Description EAST APPRDACH WOKING WEST

Number 300 35